



R4 values supplied in kit:  
 ... use 220 Ohms for supply voltage = 9V  
 ... use 510 Ohms for supply voltage = 12V  
 ... use 620 Ohms for supply voltage = 13.8V

R BIAS  
 "1%" Resistor Values (ohms)  
 for Optimum Biasing

V <sub>cc</sub>	MAR-1A
7	187
8	243
9	301
10	374
11	432
12	499
13	562
14	619
15	681
16	750
17	806
18	866
19	931
20	976

**NJQRP**  
**DDS Daughtercard**

G. Heron, N2APB Rev 1.3b 8/24/2003	Sheet 1/1
---------------------------------------	--------------